

CIVIL ENGINEERING CONSULTANTS

 1805 WATERS ROAD
 HARRISONVILLE
 MISSOURI
 64701
 816-380-5150

 FACSIMILE:
 816-884-3250
 EMAIL:
 MAIL@REOENGINEERING.COM

April 22, 2024

Attn: Kevin Higdon Kevin Higdon Construction LLC P.O. Box 847 Lee's Summit, MO 64063

> RE: R.E.O. Project 22-004-07 MD2 Plan KH-6107 Lot 148 Napa Permit #20220599 1840 SW Sage Canyon, Lee's Summit, MO

Dear Mr. Higdon,

We are providing herewith statement on the revised field bracing at the over-framed and cricket roof above the garage. At the over-framed sole plate (at the front edge of the cricket roof), a double 2x6 roof purlin is added from the front edge of the cricket extending to the rear wall of the garage. This revised purlin location shall have bracing located at 48 inches on center to the steel beam and rear wall. Braces shall be $2 \sim 2x4$ in a "tee" arrangement.

The revised bracing arrangement adequately supports the additional loads from overframed roofs above. The revised bracing is installed as described and is approved asbuilt.

Very Truly Yours,

R.E.O. ENGINEERING, P.C.

President By: Aaron D. Obermiller, P.E.

