CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20236052

Address: 3712 SW MARYVILLE PL, LEES SUMMIT, MO 640823716 SW MARYVILLE PL, LEES SUMMIT, MO

640823718 SW MARYVILLE PL, LEES SUMMIT, MO 640823710 SW MARYVILLE PL, LEES

SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Kyle Beard Failed Thursday, May 16,

Residential 2024

Corrective Action Required:

1 Miscellaneous 3710 SW Maryville. Occupancy

Correction

Kitchen receptacles are not fully installed (receptacles installed needs spark

rings installed)

3712

Passed for TCO only (pay \$50 fee associated with permit as stated below

before a TCO can be issued)

3716

Electrical face plates missing in kitchen (install spark rings in kitchen backsplash where missing) Relocated HWT has water line in contact with electrical Seal top

of A/C disconnect

3718

Electrical plate is missing at the kitchen backsplash (install spark rings in kitchen

backsplash where missing)

Pay \$50 fee associated with this permit

All units Sump pump extension are not installed Sod and splash pads are not installed

3718, 3716 and 3712 water meters are below grade. Plot plan must pass

Comments: