## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20241062Address:3513 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:	
		Kyle Beard	Not Ready	Friday, May 31, 2024	
Corrective	e Action Required:				
2	Miscellaneous Correction	5			
		-Tighten down anchor completed)	ighten down anchor bolts in basement south and west wall (not mpleted)		
		-H6 straps throughout are missing (plans specify 2 H6 straps in the pantry area and at the corner of bedroom 3. Both are still not installed according to plan)			
		Walk your property be	/alk your property before scheduling an inspection ot ready for reinspection		
		Not ready for reinspec			

Comments: