CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20240055

Address: 1020 NW PRYOR RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Robb Popp Failed Friday, June 14, 2024

Commercial

Corrective Action Required:

1 Misc Inspection incomplete

-Provide truss plans for re inspection -Install missing hold down at NE corner

-Install missing stud at NE corner

-Install all missing 3/4" anchor bolts at windows, plate breaks etc

-Bolt steel columns to top plates
-Strap top plates lapped less than 48"
-Seal all top plate penetrations
-Complete MEPs at mechanical room
**OK for insulation at demising walls only

Comments: