CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20241619

Address: 1805 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Kyle Beard Failed Thursday, June 27,

Residential 2024

Corrective Action Required:

3 Miscellaneous 1805 SW Hightown. All rough

Correction

- Electrical nail guards are needed throughout
- -Have plan designer address meaning of EC3, EC1 and load bearing option for

roof A&C

- -Truss tie down screw is missing in bath 2
- -Have plumber address the five studs drilled out for 1 1/2 waste line at

kitchen exterior load bearing wall

- -Have engineer better address (3) 2x4 at dining room window
- -Primary bedroom door is missing the header
- -Address over bored 2x10 ceiling/floor joist in basement 3 inch waste line
- -Plans call for double joist under bath tub and kitchen island (missing)
- -Electrical neutral is not connected to the bus bar in the panel
- -Nail off exterior sheeting to code

Comments: