CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20240102Address:377 NW PATCH CT, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Robb Popp	Failed	Tuesday, July 09, 2024

Corrective Action Required:

001100	ave / tetroin nequine ai	
1 Misc		-Notch discontinious posts to let in beam and complete connections per plans/ per code
		-Provide 1.5" of bearing for beam at front porch carrying roof load
		-Install or clarify 120" braced walls in garage per plan
		-Strap top plate lapped less than 24" at right side of beam in 2 car garage bay
		-Nail pony wall kickers at vaulted ceiling per plan
		-Protect dryer duct min of 2" below top plate at both sides of laundry wall
		-Fireblock tops of dead spaces in basement with approved
		matearials-INSULATION IS NOT APPROVED FOR THIS APPLICATION
		-Correct slope of master bath drain in basement joist space
		-Fireblock fur out walls at ceiling line to prevent fire spread from vertical to
		horizontal
		-Support flat framed ceiling framing at 4' max spacing

Comments: