

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20241111
Address: 2086 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Alex Fischer	Failed	Wednesday, July 17, 2024

Corrective Action Required:

1	Misc	-Missing fire blocking at base plate behind electric fireplace -Seal service cable entrance on exterior -Fire block around service cable at base plate in master bathroom -Missing fire blocking second floor HVAC chase -Trim Ufer to safe height -Fire block every 10 ft at exterior furred out basement walls (east side) -Check rafter to top plate connections appears to be missing nails
---	------	---

Comments: