

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20241067  
Address: 2087 NW OBRIEN RD, LEES SUMMIT, MO 64081

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Erosion Control</b>	Robb Popp	Failed	Friday, July 19, 2024

Corrective Action Required:

2	DCM2 ESC	7/19/24
	DEFICIENT	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS
	INSTALLATION	UNTIL ADEQUATE EROSION CONTROL PROVIDED.
		-Restore silt fence at perimeter and clean silt from street

**Comments:**