CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRSUBD20230406

Address: 1204 NE WOODS CHAPEL RD, LEES SUMMIT, MO 64064

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Sediment Control (ESC) Nick Scott Partial Tuesday, August 06,

Inspection 2024

Informational:

1 Misc 5-16-23 Site visited and it appears that there is no erosion control set up.

Please get the erosion control set up that is approved on the plans. If you

have any question please call me 816-977-5652 Nick Scott

5-19-23 NS. ESC has not been set up yet. I talked to Jeff the developer and he

said that they are working on someone to come out and put up ESC

10-25-23 NS Site visited and erosion control has failed I let the developer Jeff

know and he had some out to fix it today.

12-18-23 NS Site Visited and no erosion control issues

12-20-23 NS Site Visited and no erosion control issues

12-22-23 NS Site Visited and no erosion control issues

12-28-23 NS Site Visited and no erosion control issues

1-3-24 NS Site Visited and no erosion control issues

1-23-24 NS Site Visited and no erosion control issues

2-28-24 NS Site Visited and no erosion control issues

3-29-24 NS Site Visited and no erosion control issues

4-18-24 NS Site Visited and no erosion control issues

4-30-24 NS Site Visited and no erosion control issues

6-28-24 NS Site Visited I talked to Jeff and he is going to get the site cleaned

up and erosion control fixed.

 $7\text{-}25\text{-}24\,\text{NS}$ Site Visited and still needs a little bit of clean up but for the most

part it is clean and more erosion control has been set up.

Comments: