## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20241762

Address: 2805 SW HEARTLAND RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Friday, August 16, 2024

Residential

Corrective Action Required:

2 Misc

- -purlin supports not landing to plans above garage entry(check throughout)
- -block sheathing breaks
- -fireblock fireplace to ceiling space
- -pan return air stud bays in furr down gt rec room
- -tight all anchor bolts in basement
- -all anchor bolts to be in the middle 1/3 of sill plate
- -fireblock beam ends in basement
- -double all joist in rec room per plan
- -secure electrical raceways in furr downs

**Comments:**