

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20113001, Building Permit - Commercial Address: 1499 SW MARKET ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection -Commercial Mark Harding Passed Friday, September 30, 2011

Above Ceiling

Mike Copeland Failed Friday, September 30, 2011

Inspection

Corrective Action Required

ELECTRICAL EQUIPMENT CONTAMINATION, OPEN CEILING MISC

SPRAYED ELECTRICAL EQUIPMENT WITH PAINT. REPLACE

J-BOXES AND RECEPTICLES

Corrective Action Required

MISC FLEX DUCT SUPPORT, 2" WIDE STRAPS REQUIRED TO BE 2

SUPPORTED TO THE STRUCTURE EVERY 5 FEET OR PER

MANUFACTURER'S INSTRUCTIONS.

Corrective Action Required

MISC

PROVIDE MANUFACTURER'S INSTALLATION INSTUCTIONS FOR

TWO FURNACE UNITS.

ATTACH CONDENSATE DRAIN.

Corrective Action Required

MISC SUPPORT J BOX OVER ACCESSABLE ENTRANCE AT 2 HOUR

WALL. PROVIDE FACEPLATE IN THE SAME HALLWAY

OPPOSITE END.

Corrective Action Required

5 MISC
Corrective Action Required
6 MISC
Corrective Action Required
7 MISC

LABEL FIRE DAMPER ABOVE CEILING

GAS PIPE TO ABOVE CEILING FURNACE IS UNDER SIZED. REQUIRED TO ME A MINIMUM OF 1"

OKAY TO DROP BORDERS TILE ONLY.

Comments: