



CITY OF LEE'S SUMMIT
CODES ADMINISTRATION
220 SE GREEN ST.
P.O.BOX 1600

PHONE:
816-969-1200

FAX:
816-969-1201

Inspection Summary

Permit #: PRCOM20113001, Building Permit - Commercial
Address: 1499 SW MARKET ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Above Ceiling Inspection	Mark Harding	Failed	Tuesday, October 04, 2011

Corrective Action Required
5 MISC

SUPPORT MC OVER STAIRS, SUPPORT MC IN ROOMS ABOVE CEILING PER CODE.
CHECK THROUGHOUT

Corrective Action Required
6 MISC

LABEL FIRE DAMPER ABOVE CEILING

Corrective Action Required
7 MISC

GAS PIPE TO ABOVE CEILING FURNACE IS UNDER SIZED.
REQUIRED TO ME A MINIMUM OF 1"

OKAY TO DROP BORDERS TILE ONLY.

Comments: