

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20241067
Address: 2087 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Robb Popp	Failed	Wednesday, August 28, 2024

Corrective Action Required:

2	DCM2 ESC	8/28/24
	DEFICIENT	DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS
	INSTALLATION	UNTIL ADEQUATE EROSION CONTROL PROVIDED.
		-RESTORE SILT FENCE ST FRONT OF LOT
		-MAINTAIN GRAVEL FILTER

Comments: