## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20236080Address:2354 SW RIVER TRAIL RD, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Residential		Mitchell Schwarz	Failed	Thursday, August 29, 2024	
Correc	tive Action Required:				
1	Misc	-address holes drilled above garage -rear kitchen windows	ill check gb bracing when completed Idress holes drilled closer than 2" to one another and over bored in joists ove garage ar kitchen windows not framed to cspf specifications (see plate breaks) Idress holes bored closer than 2" to the bottom of the floor joists and each		
		other above hearth ro	• • • • •		
		<ul> <li>-stair well wall to be fr</li> </ul>	amed to plans		

**Comments:**