

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX: 816-969-1201

Inspection Summary

Permit #: PRCOM20113001, Building Permit - Commercial Address: 1499 SW MARKET ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:	
Above Ceiling Inspection	Mark Harding	Failed	Thursday, October 06, 2011	
Corrective Action Requ 1 MISC	SUPF CEILI CHEC DO N	NG PER CODE. CK THROUGHOUT 2 LO	S, SUPPORT MC IN ROOMS ABOVE CATIONS IN OFFICE ROOMS. RE PENETRATIONS ARE INSPECTED	
Corrective Action Requ 2 MISC Corrective Action Requ 3 MISC	LABE	EL FIRE DAMPER ABOV	Æ CEILING	
Final Building Inspection - Commercial	Mark Harding	Not Ready	Thursday, October 06, 2011	
Corrective Action Requ 1 MISC	MISC 10-6- 1. INS 2. INS 3. CC	ed MISC. LIST - PRE FINAL LIST ONLY NOT COMPLETE. 10-6-11 1. INSTALL GRAB BARS IN RESTROOMS PER CODE 2. INSTAL OPEN FRONT TOILET SEAT PER CODE. 3. COMPLY TO ANSI 117 CODE ON DRINKING FOUNTAIN HEIGHT AND CLEARANCE.		

4. INSTALL FIRE EXTINGUISHERS AT REQUIRED LOCATIONS.

5. LABEL FIRE DAMPER ABOVE CEILING AS PER PLANS.

6. INSTAL RETURN AIR TO FRONT ROOM FROM SOUTH AC UNIT AND INSTALL FIRE DAMPER.

7. INSTALL VINYL WALL COVERING IN BATHROOMS. OR APOXY PAINT AS REQUIRED.

8. INSTALL VINYL SCREENS ON EXTERIOR MECH. EQ.

9. EXESSIVE RISE AT STAIRS, 6 1/2" TO 5 3/4".

10. POST OCCUPANCY LOAD SIGNS.

11. PROVIDE ROOF ACCESS FOR INSPECTION.

12. BOND WATER HEATER AS PER PLANS.

13. LABEL DOOR AS PER PLANS -"DOOR SHALL REMAIN UNLOCKED."

14. PROVIDE REVISED PLANS SHOWING ALL CHANGES.

15. LABELING OF 2HR WALLS, DOORS, FRAMES.

16. PAINT ROOFTOP GAS PIPING.

17. SUPPORT AND SECURE GAS PIPING ABOVE RESTROOMS. 18. GAS LINE INSTALLED ABOVE CEILING AFTER FIRE WALLS WERE INSTALLED-INSPECTED- APPROVED--.. PROVIDE ACCES TO INTERIOR OF CEILIN/FIREWALL FOR INSPECTION OF PENETRATION. SUBMIT UL LISTING ON FIREWALL PENETRATION BEING USED.

19. LANDING AT STAIRS- SUBMIT CHANGE ON LANDING AND LOCATION OF STAIRS, PROVIDE MIN 48" LANDING AT TOP OF STAIRS FOR LANDING.

THIS IS A PRE-FINAL LIST , THIS LIST MAY BE INCOMPLETE.

Comments: