

## CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

## **Inspection Summary**

Permit #: PRCOM20113001, Building Permit - Commercial Address: 1499 SW MARKET ST, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Above Ceiling Mark Harding Failed Tuesday, October 04, 2011

Inspection

Corrective Action Required

5 MISC SUPPORT MC OVER STAIRS, SUPPORT MC IN ROOMS ABOVE

CEILING PER CODE. CHECK THROUGHOUT

Corrective Action Required

6 MISC LABEL FIRE DAMPER ABOVE CEILING

Corrective Action Required

7 MISC GAS PIPE TO ABOVE CEILING FURNACE IS UNDER SIZED.

REQUIRED TO ME A MINIMUM OF 1"

OKAY TO DROP BORDERS TILE ONLY.

## Comments: