

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20241135
Address: 3249 SW ARBOR TREE DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Control	Mitchell Schwarz	Failed	Tuesday, September 10, 2024

Corrective Action Required:
2 DCM5 ESC INSP REQUESTED INSPECTION(S) DENIED DUE TO DEFICIENT EROSION CONTROL
DENIED INSTALLATION.

NO EROSION CONTROL IN PLACE
Erosion control must be in place until sod is installed

Comments: