CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816) 969-1200 FAX (816) 969-1201

Temporary Certificate of Occupancy

Permit #:	PRRES20240573
Address:	3737 SW KNOXVILLE CT, LEES SUMMIT, MO 640823735 SW KNOXVILLE CT,
	LEES SUMMIT, MO 64082
Inspected On:	Wednesday, September 25, 2024
Inspected By:	Development Center
Expiration Date:	9/24/2024 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. **Do not cover any work until approved.**

Inspection:	Inspector:	Outcome:	Date:	
Occupancy Inspection - Codes Residential Corrective Action Required:	Kyle Beard	Ready for Temp CO	Friday, August 23, 2024	
1 Miscellaneous Correction	Both units sod, splash pads and sump pump extensions are not installed Deck is missing a joist hanger Deck joist hanger is missing nails Final grading needs to be completed before plot plan inspection can be			
	conducted Second TCO extension request was sent in by the builder. On site field inspection notes that progress is being made to finish the exterior.			
Occupancy Inspection - Codes Residential Corrective Action Required:	Kyle Beard	Ready for Temp CO	Monday, August 19, 2024	
2 Miscellaneous Correction	Both units sod, splash pads and sump pump extensions are not installed			

220 SE Green Street | Lee's Summit, MO 64063 |816.969.1200 | 816.969.1201 Fax | cityofLS.net/Development

Deck is missing a joist hanger Deck joist hanger is missing nails

Final grading needs to be completed before plot plan inspection can be conducted

Occupancy Inspection - Codes Residential		Kyle Beard	Ready for Temp CO	Wednesday, July 24, 2024	
Corrective Action Required:					
2 Miscellaneous		Both units			
	Correction	sod, splash pads and sump pump extensions are not installed			
		Deck is missing a joist hanger			
		Deck joist hanger is missing nails			
		Final grading needs to be completed before plot plan inspection can be conducted			
		ay \$75 fee associated with this permit			
		TCO passed for both units			

Comments: