CITY OF LEE'S SUMMIT

Development Services Department 220 SE Green Street Lee's Summit, MO 64063 FAX (816) 969-1201 (816) 969-1200

Temporary Certificate of Occupancy

Permit #: PRRES20235554

Address: 816 NE ALGONQUIN ST, LEES SUMMIT, MO 64064818 NE ALGONQUIN ST,

LEES SUMMIT, MO 64064814 NE ALGONQUIN ST, LEES SUMMIT, MO

64064

Inspected On: Friday, September 27, 2024

Inspected By: Development Center

Expiration Date: 10/27/2024 12:00:00 AM

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Occupancy Inspection - Codes Khanh Nguyen Ready for Temp CO Friday, September 27, 2024

Residential

1 Misc Unit 814:

Corrective Action Required:

-Complete deck. Install approved post caps at deck beam connections to posts; install hanger for upper landing cross joist connection to double joist;

return bottom end of handrail to newel post

818:

-Install two 1/2" through bolts at deck beam-post connection

**TCO approved for all units

Occupancy Inspection - Codes Shawn Hoffman Ready for Temp CO Tuesday, August 06, 2024 Residential

Corrective Action Required:

1 Misc -Sidewalk and driveway not approved on record Unit 814:

- -Sod
- -Gutter, downspout, and extensions
- -Complete deck. Install approved post caps at deck beam connections to posts; install hanger for upper landing cross joist connection to double joist; return bottom end of handrail to newel post
- -Provide sewer tracer wire port at grade

**TCO approved for unit 814 only

Corrective Action Required:

2 Misc

UNIT 818

- PROVIDE THROUGH BOLTS AT POST TO BEAM CONNECTIONS ON DECK
- ADD SUPPORT FOR DECK STAIRS
- LOWER WATER METER IN PIT TO 14-18" FROM LID
- PROVIDE SPLASH PADS
- SUMP DISCHARGE TO BE 36" AWAY FROM FOUNDATION
- PROVIDE GUTTERS AND DOWN SPOUTS
- -Provide sewer tracer wire port at grade

Occupancy Inspection - Codes Residential

Khanh Nguyen

Ready for Temp CO

Monday, July 29, 2024

Corrective Action Required:

1 Misc

-Sidewalk and driveway not approved on record

Unit 814:

- -Sod
- -Gutter, downspout, and extensions
- -Complete deck. Install approved post caps at deck beam connections to posts; install hanger for upper landing cross joist connection to double joist; return bottom end of handrail to newel post
- -Provide sewer tracer wire port at grade

Comments:

^{**}TCO approved for unit 814 and 818 only

^{**}TCO approved for unit 814 only