CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20241854Address:3820 SW RAVENGATE PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential		Kyle Beard	Failed	Wednesday, October 02, 2024
Corrective 2	Action Required: Miscellaneous Correction	installed on steps of First riser from the m allowance of 7 3/4 in Last step going to the inches of travel dista A couple of 12/2 wire A couple of 14/2 wire Hot water heater new	stairs in garage to hour 4 or more. The thresho hain living area to the k ches in height basement at the plat ince in basement needs to e in basement needs to eds a lock out installed by basement HVAC ne ights exterior siding are not installed alled as per plans	form does not have the code form does not have the code 36 o be vertically supported to code o be vertically supported to code