CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242857

Address: 1420 SW WINTHROP TER, LEES SUMMIT, MO 640811418 SW WINTHROP TER, LEES SUMMIT, MO

64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Rated Assembly Inspection Mark Harding Failed Wednesday, October

02, 2024

Corrective Action Required:

1 Miscellaneous Both sides

Correction - Spots in the field are missing fasteners and fasteners are not installed on the

edges along the rafters-

-- Screws are not set against the sheetrock.

Fully seat all screws to sheetrock to secure sheetrock against studs.

Reschedule when complete. This can be inspected during the all-rough.

Comments: