## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20241620Address:1809 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Failed	Wednesday, October 09, 2024

Corrective Action Required:

Correction Fire block gaps in garage chas Upstairs landing guard rails no Front bedroom smoke detect First to second stair riser goin 3/8 of an inch difference allow Basement stair platform does Basement handrail is not inst		Address numbers are not properly illuminated	
		Fire block gaps in garage chases	
		Upstairs landing guard rails needs to meet code height of 36 inches	
		Front bedroom smoke detector is not working correctly	
		First to second stair riser going to the basement has a greater than the code	
		3/8 of an inch difference allowance	
		Basement stair platform does not have the code 36 inches of travel distance	
		Basement handrail is not installed	
		Bottom basement stairwell does not have a light switch for proper	
		illumination	
		Electrical panel needs a receptacle within 20 feet	
		Irrigation permit is needed	
		Pay \$75 fee associated with this permit	

**Comments:**