CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20242079

Address: 1604 SW BUCKTHORN ST, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Monday, October 14,

Residential 2024

Corrective Action Required:

1 Misc

- -fire block wall space into furr down in garage (see hvac chases)
- -addressed electrical in garage no landed
- -complete bath fan wiring
- -provide stud pack at fover closet /garage wall
- -protect wiring at garage N wall
- -install LGT2 at girder R1
- -provide lateral bracing through out
- -missing truss hangers per plans. Plans do not specify certain hangers
- identified in key
- -provide hold down device at stair landing
- -anchor bolts to be tight
- -provide 3 studs at exterior wall corners in basement
- -ufer ground connection not properly installed

Comments: