CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20230994

Address: 1021 SE HAMBLEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Control Bobby Richest Partial Monday, October 14,

2024

Informational:

1 Misc 5-14-24 BR Erosion control is up and working order

5-23-24 BR Grass needs to be trim down so that public fire hydrant is visible and silt fence is visible and work properly. Also need to use approve gutter buddy's on erosion control plans for inlet protection.

5-29-24 BR Erosion control is up and working order. Grass is trim down and

public fire hydrant is visible.

6-4-24 BR Erosion control is up and working order.

6-11-24 BR Erosion control is up and working order.

6-17-24 BR Erosion control is up and working order.

6-26-24 BR Erosion control is up and working order.

7-3-34 BR Erosion control is up and working order.

7-10-24 Erosion control is up and working order.

- 7-17-24 BR Erosion control is up and working order.
- 7-26-24 BR Erosion control is up and working order.
- 8-9-24 BR Erosion control is up and working order.
- 8-15-24 BR Erosion control is up and working order.
- 8-30-24 BR Erosion control is up and working order.
- 9-4-24 BR Erosion control is up and working order.
- 9-24-24 BR Silt fence needs to be repaired on west side of property next to SE Hamblen Rd
- 10-7-24 BR Silt fence needs to be repaired on west side of property next to SE Hamblen Rd
- 10-14-24 BR Erosion control is up and working order.

Comments: