CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRCOM20232768

Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Rated Assembly Inspection Robb Popp Partial Monday, October 14,

2024

Corrective Action Required:

1 STAIR TOWER 1 Stair in building F

-1st land 2nd layer behind stringers only at all floors

-1st layer at ceiling-Hat channel at ceiling

Corrective Action Required:

2 STAIR TOWER 2 -Stair in building G

-1st and 2nd layer behind stringer only floors 1-4

Corrective Action Required:

3 STAIR TOWER 3 Stair 3 in Building J (J2)

Corrective Action Required:

4 STAIR TOWER 4 Stair 4 in Building J:

-1st and 2nd layer at stringer side only floors 1-3

-1st layer at 4th floor

Corrective Action Required:

5 STAIR TOWER 5 Stair at Building K

-1st layer stringer side only all floors

Corrective Action Required:

6 ELEVATOR 1 -1st and 2nd layer unit side behind trusses

-1st, 2nd and 3rd layer at ceiling

-Hat channel at ceiling

-1st and 2nd layer interior all floors

Corrective Action Required:

7 ELEVATOR 2

Corrective Action Required:

8 FIRST FLOOR Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at

corridor side only

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses

at corridor side only

Corrective Action Required:

9 SECOND FLOOR Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at

corridor side only

-1st layer behind tubs and showers

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses

at corridor side only

Corrective Action Required:

10 THIRD FLOOR

Building F:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses

at corridor side only

-1st and 2nd layer behind tubs and showers

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses

at corridor side only

Corrective Action Required:

11 FOURTH FLOOR

Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at

corridor side only

-1st and 2nd layer behind tubs

-RC at units and corridor

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses

at corridor side only

Building J:

-1st and 2nd layer behind tubs and showers

Comments: