

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768  
Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Tuesday, October 15, 2024

Corrective Action Required:

1	STAIR TOWER 1	Stair in building F -1st land 2nd layer behind stringers only at all floors -1st, 2nd layer at ceiling -Hat channel at ceiling
---	---------------	---

Corrective Action Required:

2	STAIR TOWER 2	-Stair in building G -1st and 2nd layer behind stringer only floors 1-4
---	---------------	--

Corrective Action Required:

3	STAIR TOWER 3	Stair 3 in Building J (J2)
---	---------------	----------------------------

Corrective Action Required:

4	STAIR TOWER 4	Stair 4 in Building J: -1st and 2nd layer at stringer side only floors 1-3 -1st layer at 4th floor
---	---------------	--

Corrective Action Required:

5	STAIR TOWER 5	Stair at Building K -1st layer stringer side only all floors
---	---------------	---

Corrective Action Required:

6	ELEVATOR 1	-1st and 2nd layer unit side behind trusses -1st, 2nd and 3rd layer at ceiling -Hat channel at ceiling -1st and 2nd layer interior all floors
---	------------	--

Corrective Action Required:

7 ELEVATOR 2

Corrective Action Required:

8 FIRST FLOOR

Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Corrective Action Required:

9 SECOND FLOOR

Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

-1st layer behind tubs and showers

-1st layer fire walls

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Corrective Action Required:

10 THIRD FLOOR

Building F:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

-1st and 2nd layer behind tubs and showers

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Corrective Action Required:

11 FOURTH FLOOR

Building F:

-1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

-1st and 2nd layer behind tubs

-RC at units and corridor

Building G:

-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only

Building J:

-1st and 2nd layer behind tubs and showers

**Comments:**