CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Commercial		Inspector:	Outcome:	Date:
		Robb Popp	Partial	Tuesday, October 15, 2024
Correctiv	e Action Required:			
1	STAIR TOWER 1	Stair tower 1 in Building F: -Shear wall nailng pattern behind stringers at floors 1-3 *OK for first layer all floors inside of stairwell -1st layer all floors		
Correctiv	e Action Required:			
2	STAIR TOWER 2	-Stair tower 2 in building G -Shear wall nailing pattern behind stringers at floors 1-2		
Correctiv	e Action Required:		-	
3	STAIR TOWER 3	-Stair tower 3 in build -Shear wall nailing pa	ding J attern behind stringers f	iloors 1-3
Correctiv	e Action Required:		Ũ	
4	FIRST FLOOR			
Correctiv	e Action Required:			
5	SECOND FLOOR	Building F: -Behind tubs and sho -Deck framing ok to c		
		dryer at corridor, stra	p top plates at back wal	
		248-Dryer duct not al dryer at corridor	lowed in 2x4 wall, top p	late overbored at dryer, protect

	247-Repair stud at laundry, install truss bracing 244-Secure nm by corridor 243-Strap top plates at LBWs 242-Install stud shoe at laundry 239-Install stud shoe at laundry 238-Tape dead sace
	237-Protect nm at island, stud shoe at laundry 236-stud shoe at laundry
Corrective Action Required:	
6 THIRD FLOOR	*Building F
	-Behind tubs and showers ok to cover -Deck framing ok to cover
	-Units and corridor approved except as noted:
	336-Complete DWV at party wall
	337-Complete DWV at party wall 343-Provide truss repair
	349-Install (3) stud shoe at corridor
Corrective Action Required:	
7 FOURTH FLOOR	*Building F -Behind tubs and showers ok to cover
	-Deck framing ok to cover
	-Units and corridor approved
	*Building J
	-Behind tubs and showers ok to cover
Corrective Action Required:	
8 ELEVATOR 1	Interior framing ok all floors

Comments: