CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:
Rated Assembly Inspection		Robb Popp	Partial	Wednesday, October 16, 2024
Correctiv	ve Action Required:			
1	STAIR TOWER 1	Stair in building F Complete		
Correctiv	ve Action Required:			
2	STAIR TOWER 2	-Stair in building G -1st and 2nd layer be	hind stringer only floors :	1-4
Correctiv	ve Action Required:			
3 Correctiv	STAIR TOWER 3 ve Action Required:	Stair 3 in Building J (J	2)	
4	STAIR TOWER 4	Stair 4 in Building J: -1st and 2nd layer at -1st layer at 4th floor	stringer side only floors 1	-3
Correctiv	ve Action Required:	,		
5	STAIR TOWER 5	Stair at Building K -1st layer stringer sid	e only all floors	
Correctiv	ve Action Required:			
6	ELEVATOR 1	-1st and 2nd layer un -1st, 2nd and 3rd laye -Hat channel at ceilin -1st and 2nd layer int	g	
Correctiv	ve Action Required:	-		
7	ELEVATOR 2			

Corrective Action Required: 8 FIRST FLOOR	Building F: -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
Corrective Action Required:	Building H: -1st layer at truss spaces pre rock
9 SECOND FLOOR	Building F: -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st layer behind tubs and showers -1st layer fire walls
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
Corrective Action Required:	Building H: -1st layer at truss spaces pre rock
10 THIRD FLOOR	Building F: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs and showers
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
Corrective Action Dequired	Building H: -1st layer at truss spaces pre rock
Corrective Action Required: 11 FOURTH FLOOR	Building F: -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs -RC at units and corridor
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
	Building H: -1st layer at truss spaces pre rock

Building J: -1st and 2nd layer behind tubs and showers

Comments: