CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20243667

Address: 2610 SW TRACKER LN, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

All Rough Inspection - Mitchell Schwarz Failed Friday, October 18,

Residential 2024

Corrective Action Required:

1 Misc -sheathing breaks to occur in the middle 24" of portal at garage

-missing perlin above garage

-provide minimum 1" clearance from B vent

-complete kitchen hood vent

-fireblock left of fire place for furr down rafter into fireplace area

-nail (3) LVL together both side above great room-missing stud at stud pack at entry /dining room corner

-plans call for 2x6 framing in entry walls

-strap top plates not overlapping at bed 3 entry

-uncover cover deck

-sister all studs where notched for anchor bolts in basement

-anchor bolts to be in the middle 1/3 of sill plate

-foundation wall studs to meet the requirements of code section R602.9

Comments: