## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20243543Address:3208 SW ARBORIDGE CIR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:
		Mitchell Schwarz	Not Ready	Tuesday, October 22, 2024
Correctiv	e Action Required:			
-anchor bolts to be within diameter of the bolt -missing hold downs on t -provide hangers for cut -fire block hvac chase rig -block sheathing break at -address plans call for (3) -complete electrical in be -missing lateral bracing t -nail double trusses to pl -minimum 3 studs at exter- sister all overmatched s		ato ceiling space vall into ceiling space(seal gaps) ain 12" of plate breaks but not closer than 7x the trusses (check throughout) t joists above great room cut for dwv ght of great room windows at front entry B) 2x4 full height at great room/ stairwell wall oed 3 and fireblock throughout blans throughout terior wall corners in basement		

Comments: