## CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20243851

Address: 2139 NW KILLARNEY LN, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

**Erosion Control** Robb Popp Failed Thursday, October 24,

2024

Corrective Action Required:

DEFICIENT EROSION CONTROL INSTALLATION. NO FURTHER INSPECTIONS 1 DCM2 ESC

DEFICIENT UNTIL ADEQUATE EROSION CONTROL PROVIDED.

INSTALLATION

-RESTORE SILT FENCE

Corrective Action Required:

DCM3 ESC 10/24/24

> REQUIRED 2 DAY EROSION CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE

> > WITHIN TWO BUSINESS DAYS.

## Comments: