CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20240647

Address: 3710 SW CLAYTON PL, LEES SUMMIT, MO 640823712 SW CLAYTON PL, LEES SUMMIT, MO

640823716 SW CLAYTON PL, LEES SUMMIT, MO 640823718 SW CLAYTON PL, LEES

SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Erosion Control Dustin Agcopra Failed Monday, November

04, 2024

Informational:

1 Miscellaneous Full erosion control measures are in place and must be maintained until CofO

Correction

Corrective Action Required:

2 DCM3 ESC 11-4-24 Dustin A, all sws have silt due to improper erosion control..EROSION

REQUIRED 2 DAY CONTROL REQUIRED. EROSION CONTROL SHALL BE IN COMPLIANCE WITHIN

TWO BUSINESS DAYS.

Comments: