

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20244953
Address: 1909 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Wednesday, November 13, 2024

Corrective Action Required:

2	Miscellaneous Correction	<ul style="list-style-type: none">- Garage PFH anchor bolts are not located within the center 1/3 of the bottom plate- Garage PFH anchor bolts are not tightened down to the bottom plate- Exterior garage PFH sheeting passed and is okay to cover
---	--------------------------	---

Comments: