CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRSUBD20222424 Address: 1400 SE RANSON RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Erosion Sediment Control (ESC) Inspection	Bobby Richest	Failed	Thursday, September 26, 2024
Informational:			
	2-20-24 BR Erosion control is partially working need to add more silt fence on Ranson Rd side of the property.		
	2-22-24 BR Erosion control is up and working order.		
	2-29-24 BR Erosion control	is up and working order.	
	3-8-24 BR Erosion control is	s up and working order.	
	3-15-24 BR Erosion control	is up and working order.	
	3-20-24 BR Erosion control	is up and working order	
	3-25-24 BR Erosion control	is up and working order.	
	4-3-24 BR Erosion control is up and working order.		
	4-10-24 BR Erosion control	is up and working order.	
	4-15-24 BR Erosion control	is up and working order.	

4-23-24 BR Erosion control is up and working order.

5-2-24 BR Erosion control is up and working order.

5-6-24 BR Erosion control is up and working order.

5-15-24 BR Erosion control is up and working order.

5-21-24 BR Erosion control is up and working order.

5-23-24 BR Grass needs to be trim on SE Ranson Rd due to grass has covered up silt fence.

6-3-24 BR Erosion control is up and working order grass has been trim to a acceptable height.

6-21-24 BR Erosion control is up and working order.

6-26-24 BR Erosion control is up and working order.

7-3-34 BR Erosion control is up and working order.

7-10-24 BR Erosion control is up and working order.

7-17-24 BR Erosion control is up and working order.

7-27-24 BR Erosion control is up and working order.

8-5-24 BR Need to repair missing section of silt fence on SE Ranson Rd.

8-15-24 BR Need to repair missing section of silt fence on SE Ranson Rd.

8-29-24 BR Need to repair missing section of silt fence on SE Ranson Rd.

9-26-24 BR Need to repair missing section of silt fence on SE Ranson Rd.

10-7-24 BR Need to repair missing section of silt fence on SE Ranson Rd.

10-23-24 BR Erosion control is up and working order.

Comments: