

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768  
Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>Rated Assembly Inspection</b>	Robb Popp	Partial	Friday, November 15, 2024

Corrective Action Required:

1	STAIR TOWER 1	Stair in building F Complete
---	---------------	---------------------------------

Corrective Action Required:

2	STAIR TOWER 2	-Stair in building G -1st and 2nd layer behind stringer all floors -1st layer all floors
---	---------------	--

Corrective Action Required:

3	STAIR TOWER 3	Stair 3 in Building J (J2)
---	---------------	----------------------------

Corrective Action Required:

4	STAIR TOWER 4	Stair 4 in Building J: complete
---	---------------	------------------------------------

Corrective Action Required:

5	STAIR TOWER 5	Stair at Building K -1st layer stringer side only all floors
---	---------------	---

Corrective Action Required:

6	ELEVATOR 1	-1st and 2nd layer unit side behind trusses -1st, 2nd and 3rd layer at ceiling -Hat channel at ceiling -1st and 2nd layer interior all floors -1st layer at unit side
---	------------	---

Corrective Action Required:

7            ELEVATOR 2            1st layer, 2nd, 3rd layer and hat channel at ceiling  
1st and 2nd layer all floors interior

Corrective Action Required:

8            FIRST FLOOR            Building F:  
-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only  
-1st layer at 2 stairs and firewall  
-RC at walls and ceilings except 166  
-Screw pattern at wall and ceiling approved except at G157 and elevator  
-2nd layer around elevator and at 2-hr wall between F and G

Building G:  
-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only  
-1st and 2nd layer behind tubs and showers

Building H:  
-1st and 2nd layer at truss spaces pre rock

Building J:  
-1st layer behind tubs and showers

Corrective Action Required:

9            SECOND FLOOR            Building F:  
-1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only  
-1st layer behind tubs and showers  
-1st and 2nd layer fire walls  
-RC at units and corridor  
-Screw pattern at units and corridor

Building G:  
-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only  
-1st and 2nd layer behind tubs and showers

Building H:  
-1st layer at truss spaces pre rock

Building J:  
-1st layer behind tubs and showers

Corrective Action Required:

10            THIRD FLOOR            Building F:  
-1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only  
-1st and 2nd layer behind tubs and showers  
-1st layer at shear walls and 2 hour walls  
-RC at units and corridors  
-Screw pattern at units and corridor

Building G:

- 1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
- 1st and 2nd layer behind tubs

Building H:

- 1st layer at truss spaces pre rock

Building J:

- 1st and 2nd layer behind tubs and showers

Corrective Action Required:

11

FOURTH FLOOR

Building F:

- 1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
- 1st and 2nd layer behind tubs
- RC at units and corridor
- \*\*Screw pattern at units and corridor except at elevator

Building G:

- 1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only
- Pre-rock 2nd layer behind showers at units 2424,2426,2434, and 2435

Building H:

- 1st and 2nd layer at truss spaces pre rock

Building J:

- 1st and 2nd layer behind tubs and showers

**Comments:**