CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20240726Address:2234 SW CROWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
Occupancy Inspection - Codes Residential	Kyle Beard	Failed	Monday, November 25, 2024

Corrective Action Required:

2	Miscellaneous	-Front porch GFCI receptacle is not fully secured into the wall within the
	Correction	protective bubble
		-Remove dust cover from basement CO detector
		-Seal top of AC disconnect
		-Water meter height in pit could not be inspected because of water in the pit

Comments: