CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Rated Assembly Inspection		Inspector:	Outcome: Partial	Date: Monday, November 25, 2024
		Robb Popp		
Correctiv	e Action Required:			
1	STAIR TOWER 1	Stair in building F Complete		
Correctiv	e Action Required:			
2	STAIR TOWER 2	-Stair in building G Complete		
Correctiv	e Action Required:			
3	STAIR TOWER 3	Stair 3 in Building G -Complete		
Correctiv	e Action Required:			
4	STAIR TOWER 4	Stair 4 in Building J: complete		
Correctiv	e Action Required:			
5	STAIR TOWER 5	Stair at Building K -1st layer stringer side o	nly all floors	
Correctiv	e Action Required:			
6	ELEVATOR 1	-1st and 2nd layer unit si -1st, 2nd and 3rd layer at -1st and 2nd layer interio -1st, 2nd layer at unit sic	t ceiling or all floors	
Correctiv	e Action Required:			
7	ELEVATOR 2	1st layer,2nd, 3rd layer a	ind hat channel at ceiling	

		1st and 2nd layer all floors interior 3 walls -1st and 2nd layer outside all floors -1st layer inside at 4th and 2nd
Corrective	e Action Required:	
8	FIRST FLOOR	Building F: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st layer at 2 stairs and firewall -RC at walls and ceilings except 166 -Screw pattern at wall and ceiling approved except at G157 and elevator -2nd layer around elevator and at 2-hr wall between F and G
Corrective 9	e Action Required: SECOND FLOOR	 Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs and showers Building H: -1st and 2nd layer at truss spaces pre rock -1st and 2nd layer at firewall extensions at deck Building J: -1st and 2nd layer behind tubs and showers Building F: -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer fire walls -RC at units and corridor Screw pattern at units and corridor Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs and showers
Corroctiv		Building J: -1st and 2nd layer behind tubs and showers
10	e Action Required: THIRD FLOOR	Building F: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs and showers -1st layer at shear walls and 2 hour walls

	-RC at units and corridors -Screw pattern at units and corridor
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs
	Building H: -1st layer at truss spaces pre rock -1st and 2nd layer at firewall extensions at deck
Corrective Action Beguired	Building J: -1st and 2nd layer behind tubs and showers
Corrective Action Required: 11 FOURTH FLOOR	Building F: -1st layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -1st and 2nd layer behind tubs -RC at units and corridor **Screw pattern at units and corridor except at elevator
	Building G: -1st and 2nd layer at truss space at firewall, stairwell and elevator for trusses at corridor side only -Pre-rock 2nd layer behind showers at units 2424,2426,2434, and 2435 -1st layer at firewalls
	Building H: -1st and 2nd layer at truss spaces pre rock -1st and 2nd layer behind tubs and showers -1st and 2nd layer at firewall extensions at deck
	Building J: -1st and 2nd layer behind tubs and showers
Corrective Action Required: 12 ELEVATOR 3	-1st layer at (3) interior walls -1st, hat channel and 2nd layer at ceiling

Comments: