CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20242722Address:2303 SW SERENA PL, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Tuesday, November 26, 2024
Corrective Action Required: 1 Misc	- unable to verify nail pattern on portal fram covered		
	- Anchor bolt required within 12" of plate breaks/ single garage		
	 Add stud under triple 18" LVL at stairs and owner entry and nail off stud pack **Nail 16d@24" oc or equivalent 		
	- No support under valley rafter low side at dining/ great return wall **Not done		
	- Support ridge over master bathroom and provide collor ties **Provide collar ties at 4 ft oc near upper ridge		
	 Fire block vertically every 10' at basement stairs wall **Not done 		
	-Addenum: Fb master bedroom, laundry, and front bedroom walls from attic		
	 Provide joist hangers basement at stairs **Not done at (3)2x10 connection near upper landing 		
	- Provide anchor bolts with in 12" of plate breaks at basement unfinished by		

bedroom 4 (2) locations **Not done

**DO NOT INSULATE

Comments: