## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #:PRRES20243932Address:3441 SE CORBIN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Shawn Hoffman	Failed	Monday, December 16, 2024
Corrective Action Required:			
3 Misc	<ul> <li>Tighten anchor bolts garage</li> <li>Seal gaps in fire blocking South east side of garage fir out</li> <li>Fire block top plate gaps around steel beam in garage</li> <li>Missing anchor bolt at sill in bathroom near owner entry</li> <li>Minimum of 3 studs required at exterior corners, north East cripple wall</li> <li>Fire block large gap above top plate over windows in rec room</li> <li>Fire block top plate of A/C chase in rec room</li> <li>Anchor sill plate at bathroom off owner entry</li> <li>Nail off stud packs at stairs supporting LVL</li> <li>Snow block roof line at bedroom 1 and walk in closet</li> <li>Damaged girder G1 on South end</li> <li>Provide lateral bracing for gable truss South side</li> <li>No pressure on gas line gauge</li> </ul>		

Comments: