CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20241493Address:2120 NW OBRIEN RD, LEES SUMMIT, MO 64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: All Rough Inspection - Residential		Inspector:	Outcome:	Date:
		Robb Popp	Not Ready	Wednesday, December 18, 2024
Corrective	Action Required:			
1	Miscellaneous Correction	Garage PFH sheeting break should be located within 24 inches of the middle 1/3 of garage portal leg		
		This inspection was for a garage PFH only		
Corrective	Action Required:			
2	Misc	12/11/24 -Inspection denied. No ac -Clean debris from street 12/18/24 -No change, inspection de		

Comments: