## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20245503

Address: 2619 SW BARLEY FIELD DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

All Rough Inspection - Mitchell Schwarz Failed Monday, December

Residential 23, 2024

## Corrective Action Required:

2 Misc

- -provide Boca plate protection for dwv at laundry top and bottom plate
- -seal penetration in primary suite top plate near R/a
- -provide 3000# hold down per plans at rear door
- -provide floor joist at stairwell wall for floor joists in basement
- -provide Boca plate protection for dwv in wet bar area
- -seal penetrations in vertical to horizontal fire blocking every 10'
- -complete panning in furr down for for R/A joist space
- -pack insulation in tightly and securely above window above basement  $% \left( 1\right) =\left( 1\right) \left( 1\right) +\left( 1\right) \left( 1\right) \left( 1\right) +\left( 1\right) \left( 1\right) \left($
- bedroom
- -missing nails in hanger above basement bedroom

**Comments:**