## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #: PRCOM20232768 Address: 810 NW WARD RD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:		Inspector:	Outcome:	Date:	
All Rough Inspection - Commercial		Shawn Hoffman	Partial	Tuesday, January 14, 2025	
Correctiv	e Action Required:				
1 STAIR TOWER 1		Stair tower 1 in Building F: -Shear wall nailng pattern behind stringers at floors 1-3 *OK for first layer all floors inside of stairwell -1st layer all floors			
Corrective Action Required:					
2	STAIR TOWER 2	-Stair tower 2 in building G -Shear wall nailing pattern -Framing approved at all f	behind stringers at floors 1-	-2	
Corrective Action Required:		0 11			
3	STAIR TOWER 3	-Stair tower 3 in building J -Shear wall nailing pattern	behind stringers floors 1-3		
Correctiv	e Action Required:		-		
4	FIRST FLOOR	Building F Complete except as noted 157-NOT READY 389-Walls only ok-comple	: te meps at ceiling and seal d	ead space	
		Building G: - Seal ceiling penitrations i -Behind tubs and showers -Balconies ok to cover	n mechanical room at line so for pre rock	et throughput	

	- Inspected 4 soffit fur outs
	<ul> <li>118 fire caulk top plate penitrations at tension rods</li> <li>421 and 422 not ready</li> <li>Mechanical closet-walls only ok to cover</li> </ul>
	Basement:- -Seal draft stops between garages, complete chase walls, furdowns and fireblocking
	Building H: -patios ok to cover -Behind tubs and showers ok to cover
	Building J: -Balconies ok to cover -Behind tubs and showers ok to cover
Corrective Action Required: 5 SECOND FLOOR	Building F: Complete except as noted: -Units and corridor complete
	Building G: -Behind tubs and showers for pre rock -Balconies ok to cover - Fire caulk DWV in coridor near 217
	Building H: -patios ok to cover -Behind tubs and showers ok to cover
	In corridor-support and secure SER cables throughout, seal draft stops and 2 hour walls 221-Support and secure SER cables, seal penetrations 222-Install fire collar at dead space 220-Strap corridor wall at line set, support/ secure ser cables 216-Protect dryer box at party wall
	Building J: -Balconies ok to cover -Behind tubs and showers ok to cover
Corrective Action Required: 6 THIRD FLOOR	*Building F -Units and corridor approved
	Building G: -Units and corridor approved
	Building H:

		-Units and corridor approved
Corrective	Action Required:	Building J: -Balconies ok to cover -Behind tubs and showers ok to cover
7	FOURTH FLOOR	*Building F -Units and corridor approved
		*Building G:
		Units and corridor complete
		-Balconies ok to cover
		Building H:
		-South side patios ok to cover
		-Behind tubs and showers ok
		-Patios ok to cover
		-Units and corridor approved
		Building J:
		-Balconies ok to cover
		-Behind tubs and showers ok to cover
Corrective	Action Required:	
8 Corrective	ELEVATOR 1 e Action Required:	Interior framing ok all floors
9	ELEVATOR 2	Elevator in G:
		Framing approved

Comments: