## CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 DEVSERVICES.CITYOFLS.NET

## **Inspection Summary**

Permit #:PRRES20242123Address:2508 NE WOODLAND OAK CIR, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Khanh Nguyen	Failed	Monday, January 27, 2025
Corrective Action Required:			
1 Misc	-Nail front ZIP sheathing **The ZIP board outside the front office is not nailed properly (8d@12" in field)		
	<ul> <li>Engineer address support for ridge and hips above loft **The plan does not show the vault connection detail that it refers to on the same sheet</li> </ul>		
	-Missing lvl beam under kitchen <b>**</b> Is there an LVL beam under the bearing wall? Verify		
	**OK TO INSULATE		

## Comments: