

CITY OF LEE'S SUMMIT CODES ADMINISTRATION 220 SE GREEN ST. P.O.BOX 1600

PHONE: 816-969-1200

FAX:

816-969-1201

Inspection Summary

Permit #: PRCOM20114943, Building Permit - Commercial

Address: 120 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086

This work has been inspected and the inspection results noted below. Please call for re-inspection once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date:

Concrete Walls and John Borns Partial Tuesday, November 29, 2011

Columns Inspection

Corrective Action Required

MISC WALLS OK TO POUR WHEN READY AT FOLLOWING LOCATIONS:

CROSSWALL AT (CC) BETWEEN STAIR AND ELEVATOR SHAFTS

AT 1ST LEVEL; ENTIRE FIRST FLOOR ELEVATOR

Corrective Action Required

MISC CONCRETE COLUMNS AT FOLLOWING LOCATIONS OK TO POUR

> WHEN READY: T1/7, T1/6, BB.5/5.9, BB.5/5.2, BB.5/4.7, DD/5.9, DD/5.2, DD/4.7; T2/7; T4/7; T5/7; T5/6; BB/3.7; BB/2.7; A.5/2.7; T6/7;

T6/6; T4/6; T3/6;

Concrete Walls and John Borns Partial Tuesday, November 29, 2011

Columns Inspection

Corrective Action Required

WALLS OK TO POUR WHEN READY AT FOLLOWING LOCATIONS: **MISC**

CROSSWALL AT (CC) BETWEEN STAIR AND ELEVATOR SHAFTS

AT 1ST LEVEL; ENTIRE FIRST FLOOR ELEVATOR

Corrective Action Required

MISC CONCRETE COLUMNS AT FOLLOWING LOCATIONS OK TO POUR

WHEN READY: T1/7, T1/6, BB.5/5.9, BB.5/5.2, BB.5/4.7, DD/5.9,

DD/5.2, DD/4.7; T2/7; T4/7; T5/7; T5/6; BB/3.7; BB/2.7; A.5/2.7;

Comments: