CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200 **DEVSERVICES.CITYOFLS.NET**

Inspection Summary

Permit #:PRRES20245813Address:1937 SW HIGHTOWN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspectio	n:	Inspector:	Outcome:	Date:
Erosion Co Residenti	ontrol Inspection al	Kyle Beard	Failed	Tuesday, February 11, 2025
Corrective Action Required: 2 DCM1 ESC REQUIRED NO FURTHER INSP		EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.		
		02/24/25 Jamie S, Silt fence is down in multiple spots requires fixing.		
		Silt fence is still damaged KBEARD	and is missing along the lot	lines. 02/11/25

Comments: