

CITY OF LEE'S SUMMIT  
Development Services Department  
220 SE Green Street  
Lee's Summit, MO 64063  
(816)969-1200  
**DEVSERVICES.CITYOFLS.NET**

## Inspection Summary

Permit #: PRRES20245637  
Address: 4421 SW GRINDSTONE CIR, LEES SUMMIT, MO 64082

---

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
<b>All Rough Inspection - Residential</b>	Kyle Beard	Failed	Tuesday, February 11, 2025

Corrective Action Required:

2	Miscellaneous Correction	- Exterior garage PFH sheathing failed inspection - Sheathing does not extend to both top plates. See bracing detailed in plans on page S530 illustration #5
---	--------------------------	---

This inspection was for a exterior garage PFH only

**Comments:**