

CITY OF LEE'S SUMMIT
Development Services Department
220 SE Green Street
Lee's Summit, MO 64063
(816)969-1200
DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245539
Address: 1625 SW ARBORWAY TER, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection:	Inspector:	Outcome:	Date:
All Rough Inspection - Residential	Kyle Beard	Failed	Tuesday, February 18, 2025

Corrective Action Required:

2	Miscellaneous Correction	Nail missing in joist hanger at great room to foyer LVL Windows not installed in stairwell Remove all insulation netting from upstairs exterior walls for inspection Bathroom 3 vent fan flex pipe is broken Fire block top plate in master bedroom north wall Second truss tie down screw is not installed in master closet at girder beam Truss tie down screws are missing in bedroom 2 Anchor bolts in basement do not seem to be properly installed into the bottom plate in several areas
---	--------------------------	----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Comments: