



LEE'S SUMMIT, MISSOURI FIRE DEPARTMENT LOSS REDUCTION PROGRAM



NOTIFICATIONS/CONTACT INFORMATION SECTION

PAGE 1

☐ CHANGES

BUSINESS NAME	SAINT LUKES EAST		
ADDRESS	100 NE SAINT LUKES BLVD, LEES SUMMIT, MO 64086		
OWNER/OPERATOR NAME	TURNER CONSTRUCTION CO:	TELEPHONE	(816) 283-0555
ADDRESS	2345 GRAND BOULEVARD SUITE 1000		
	KANSAS CITY, MO 64108		
	Primary: (816) 283-0555		
	Cell: (816) 918-6040		

EMERGENCY CONTACT INFORMATION

NAME	TELEPHONE
1.	
2.	
3.	
4.	

LOSS REDUCTION TYPE

☒ Occupancy	☐ Semi-Annual	☐ Annual	☐ Life Safety	☐ Sprinkler	☐ Hazardous Material Permit
☐ Complaint	☐ Explosive Storage	☐ UST	☐ Post-Incident	☐ Open Burning	☐ Other
CLASS: I-2	Map#: 175X	PFA#:	KNOX BOX:	KNOX LOCATION:	PERMIT # prcom20110759

LOSS REDUCTION NARRATIVE

☐ NO CORRECTIONS NOTED

☐ ALL CORRECTIONS COMPLETED

Last Inspection 1st Inspection 10/12/11 2nd Inspection 12/5/11 3rd Inspection 4th Inspection

INSPECTION	INSPECTOR	OUTCOME	DATE
Occupancy Inspection - Fire	Joe Dir	Passed	Monday, December 05, 2011
ALL PENDING ISSUES WERE CORRECTED: labeling needed for the electrical room			
Alarm Test	Joe Dir	Passed	Tuesday, October 11, 2011
Sprinkler - Hydrostatic Test	Joe Dir	Passed	Friday, October 07, 2011
Sprinkler - Flow Test	Joe Dir	Passed	Friday, October 07, 2011
Occupancy Inspection - Fire	Joe Dir	Temporary C of O	Wednesday, October 12, 2011
Corrective Action Required:			
1 (1) Coordinate the testing of the emergency lighting and the exit signs with the generator test.			

- (2) Coordinate the duct detection test with the HVAC contractor.
- (3) program the delayed egress doors to activate on the depression of the panic bar.
- (4) uncover the smoke detectors throughout as the construction dust allows
- (5) provide the medical gas line test summary

DATE OF REPORT	INSPECTOR	PREVENTION FOLLOW-UP REQUIRED?	RESPONSIBLE SIGNATURE
December 05, 2011	Joe Dir	☐ Yes ☒ No	