## CITY OF LEE'S SUMMIT **Development Services Department** 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

## **DEVSERVICES.CITYOFLS.NET**

## **Inspection Summary**

Permit #: PRRES20242858

Address: 1426 SW WINTHROP TER, LEES SUMMIT, MO 640811424 SW WINTHROP TER, LEES SUMMIT, MO

64081

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Inspector: Outcome: Date: All Rough Inspection -Khanh Nguyen Failed Monday, February 24, Residential

Corrective Action Required:

1 Misc 1426:

-The 9.25" lvl beam below is not aligned with the 16" lvl roof beam

-Protect fireplace csst gas line at wall sole plate for min 5" with proper strike plate per Wardflex instructions \*\*Need the close the gap between the nail plates

-Move the parallel NM cable out of the return air space above basement rec rm

2025

and seal return air space

-Protect DVW pipe at bathroom bottom wall plate with BOCA plate

-Split joist at bedroom 3 near foundation wall \*\*Secure NM cable per code -Bond panel enclosure to the EGC bus bar. Install the missing bonding screw

824-OK TO ROCK

**Comments:**