CITY OF LEE'S SUMMIT Development Services Department 220 SE Green Street Lee's Summit, MO 64063 (816)969-1200

DEVSERVICES.CITYOFLS.NET

Inspection Summary

Permit #: PRRES20245549

Address: 1933 SW MERRYMAN DR, LEES SUMMIT, MO 64082

This work has been inspected and the inspection results noted below. Please schedule inspections once all corrective actions have been completed. Do not cover any work until approved.

Inspection: Outcome: Date:

Erosion Control Inspection Kyle Beard Failed Tuesday, March 04,

Residential 2025

Corrective Action Required:

2 DCM1 ESC EROSION CONTROL REQUIRED. NO FURTHER INSPECTIONS WILL BE

REQUIRED NO PERFORMED UNTIL EROSION CONTROL IS INSTALLED AND IN COMPLIANCE.

FURTHER INSP

Install front gravel filter

Comments: